

**IN THE STATE COURT OF COBB COUNTY
STATE OF GEORGIA**

**KENNETH DAVID MELTON and
MARY ELIZABETH MELTON,
Individually, and as Administrators
of the Estate of JENNIFER
BROOKE MELTON, deceased,**

Plaintiffs,

**GENERAL MOTORS LLC, and
THORNTON CHEVROLET, INC.,**

Defendants.

**CIVIL ACTION
FILE NO.**

14A-1197-4

14 MAY 12 AM 9:22
ANGIE T. DAVIS
STATE COURT CLERK-13

COBB COUNTY GA
FILED IN OFFICE

COMPLAINT

Plaintiffs Kenneth D. Melton and Mary E. Melton (the "Meltons") bring this action individually, and as Administrators of the Estate of Jennifer Brooke Melton, ("Brooke"), against Defendants General Motors, LLC ("GM") and Thornton Chevrolet, Inc. ("Thornton"):

I. Summary of Claims

1. This is an action for wrongful death, strict product liability, negligence, and fraudulent concealment. The Meltons bring the action individually and as Administrators of the Estate of Jennifer Brooke Melton, who was severely

injured in the single vehicle crash of a 2005 Chevrolet Cobalt on March 10, 2011, and who died shortly thereafter.

2. GM is one of the largest car and truck manufacturers in the United States. It designed and manufactured the 2005 Chevrolet Cobalt that is at issue in this case, along with over a million other similar cars. All of these cars contained the same safety-related defects.

3. More than nine years before Brooke's injury and death, GM knew about the safety-related defects in the Chevrolet Cobalt, and did nothing to recall or fully remedy the defects or warn users about them. Rather, GM intentionally, purposely, fraudulently, and systematically concealed the defects from the Meltons and Brooke, the National Highway Traffic Safety Administration ("NHTSA"), and the driving public.

4. GM's misconduct, fraudulent concealment, and systematic concealment of the safety-related defects, toll the statute of limitations that might otherwise be applicable to this action.

5. Thornton, the Chevrolet car dealership that serviced Brooke's car right before her death, knew of the problems that Brooke was having with her Chevrolet Cobalt. It undertook to repair her car, repaired the wrong parts, overlooked a critical GM Technical Safety Bulletin, performed unnecessary and

ineffective repairs, failed to test drive it, and without repairing her car returned it to Brooke as "repaired."

II. Parties, Jurisdiction, and Venue

6. The Meltons are citizens of Georgia and reside in Cobb County, Georgia. They are the lawfully appointed Administrators of the Estate of Jennifer Brooke Melton.

7. GM is a Delaware limited liability company doing business in all fifty states with its principal place of business in Detroit, Michigan. GM does business in this district and division and maintains its registered agent here as well. GM is the successor corporation to General Motors Corporation, which underwent bankruptcy in 2009. Through that bankruptcy and asset sale from GMC to GM, GM assumed the liabilities of GM as set out herein. GM may be served via its registered agent CSC of Cobb County, 192 Anderson Street, S.E., Suite 125, Marietta, GA 30060.

8. GM is subject to the jurisdiction of and venue in this Court.

9. Defendant Thornton is a corporation organized and existing under the laws of the State of Georgia, having as its principal place of business, 1971 Thornton Road, Lithia Springs, Douglas County, Georgia 30122-2633. Thornton's registered agent for service of process is John W. Thornton, 1971 Thornton Road, Lithia Springs, Georgia, 30122.

10. Defendant Thornton is subject to the jurisdiction of and venue in this Court.

11. The Meltons renew their action against Thornton pursuant to O.C.G.A. § 9-2-61, and show that they have not previously dismissed their case against Thornton in state or federal court. Renewal under O.C.G.A. § 9-2-61 is thereby appropriate and proper, and this Court has jurisdiction over Thornton as a result.

III. Facts

The Purchase of the 2005 Chevrolet Cobalt

12. On August 31, 2005, Brooke Melton purchased the 2005 Chevrolet Cobalt from Bill Heard Chevrolet in Cobb County, Georgia.

The Wreck and Brooke's Injury and Death

13. On March 10, 2010, Brooke was driving her 2005 Chevrolet Cobalt north on Georgia Highway 9. She was wearing her lap/shoulder belt.

14. Because of the nature of the crash, the known safety-related defects in the 2005 Chevrolet Cobalt caused the key in Brooke's car to turn from the run to accessory/off position as she was driving on Highway 9. Once the key turned, the engine shut off. The safety-related defects in the Cobalt shut off her power steering, and greatly reduced her braking power and function. As a result

of the engine shutting off, Brooke lost control of the Chevrolet Cobalt, crossed the center lane, and was struck by a car driven by Shannon Jones.

15. Only 29 years old at the time, Brooke suffered a catastrophic brain injury and died the evening of the crash.

GM's Knowledge of Safety-Related Defects In The Chevrolet Cobalt and Its Concealment of Them

16. The 2005 Chevrolet Cobalt has safety-related design defects. First, a low torque detent in the ignition switch allows the key to be inadvertently turned from the run to accessory/off position. Second, because of the low position of the key lock module on the steering column, a driver can inadvertently bump the key fob or chain which results in the key turning from run to the accessory/off position. Third, the key sold with the Cobalt has a slot design which allows the key fob or chain to hang lower on the key and increases the chance of the key inadvertently moving from the run to accessory/off position during ordinary driving maneuvers. The design of the ignition switch, position of the key lock module, and slot design of the key are hereinafter referred to as the "Key System."

17. In 2001, during developmental testing of the 2003 Saturn Ion, GM learned that the engines in those cars were stalling due to defects in the Key System. GM chose not to fix the defects.

18. In 2002, GM began manufacturing and selling 2003 Saturn Ions with the defective Key System. It later began selling Chevrolet Cobalts with the same defective Key System.

19. In 2004, GM engineers reported that the ignition switch on the Saturn Ion was so weak and so low on the steering column that a driver's knee could easily bump the key and turn off the car.

20. This defect was sufficiently serious for a GM engineer, in January 2004, as part of GM's vehicle evaluation program, to affirmatively conclude, in writing, that "[t]his is a basic design flaw and should be corrected if we want repeat sales."

21. In 2004, GM began manufacturing and selling the 2005 Chevrolet Cobalt. The Cobalt was a sister vehicle (essentially the same car with a different badge or name) of the Saturn Ion. As noted, GM installed the same Key System on the 2005 Cobalt as it did on the Saturn Ion.

22. On October 29, 2004, around the time of GM's market launch of the 2005 Cobalt, Gary Altman – GM's program-engineering manager for the Cobalt – test drove the Cobalt with the standard key and key fob. During the test drive, when Altman's knee bumped the key, the engine turned off, causing the engine to stall. Altman reported this incident to GM.

23. In response to Altman's report, GM launched an engineering inquiry to investigate the potential for the key to move from the "run" to the "accessory/off" position during ordinary driving conditions. This inquiry is known within GM as a Problem Resolution Tracking System Inquiry ("PRTS"). The specific complaint which resulted in the PRTS was that the "the vehicle can be keyed off with knee while driving."

24. On February 1, 2005, as part of the PRTS, GM engineers concluded:

There are two main reasons that [sic] we believe can cause a lower effort in turning the key: 1. A low torque detent in the ignition switch. 2. A low position of the lock module in the column. (PRTS – Complete Report N172404).

25. As part of the PRTS, GM engineers also began looking into ways to solve the problem of the key moving from the "run" to the "accessory/off" position during ordinary driving.

26. On February 18, 2005, GM engineers presented several possible solutions to the Cockpit Program Integration Team ("CPIT"). GM engineers determined the only "sure solution" to fixing the problem of the key inadvertently moving from the "run" to the "accessory/off" position required changing from a low mount to a high mount lock module, which would considerably reduce the possibility of the key/key fob being impacted by a driver.

27. According to GM engineers, this change in the key position on the lock module, **combined with** increasing the detent in the ignition switch, would be a “sure solution.” GM, however, through Altman, rejected this “sure solution,” in part, because the cost to implement the solution would be too high.

28. During this PRTS, GM also considered changing the key from a slot to a hole as a way to attempt to contain this problem, but not as a solution to the problem.

29. Changing the key from a slot to a hole would reduce the lever arm of the key and the key chain. With the slot design, the key chain would hang lower on the key which would increase the torque force on the ignition switch when the chain was contacted or moved in any way. GM engineers determined this key change would significantly reduce the chance of the key inadvertently moving from the “run” to the “accessory/off” position during ordinary driving maneuvers.

30. A GM engineer conducted a cost analysis of this key change and determined that the cost to make this change would be less than one dollar per vehicle or around 57 cents per part.

31. GM, however, rejected this proposed key change and, on March 9, 2005, GM closed the PRTS without taking any steps to fix the defective Key System in Ions and Cobalts. The PRTS detailed the reasons why GM took no action.

Per GMX001 PEM's [Gary Altman] directive we are closing this PRTS with no action. The main reasons are as following: All possible solutions were presented to CPIT and VAPIR: a. The lead-time for all the solutions is too long. b. The tooling cost and piece price are too high. c. None of the solutions seem to fully countermeasure the possibility of the key being turned (ignition turn off) during driving. Thus **none of the solutions represents an acceptable business case.** (emphasis added)

32. On February 28, 2005, GM issued a bulletin to its dealers regarding engine-stalling incidents in 2005 Cobalts and 2005 Pontiac Pursuits (the Canadian version of the Pontiac G5).

33. The February 28, 2005, bulletin addressed the potential for drivers of these vehicles to inadvertently turn off the ignition due to low key ignition cylinder torque/effort.

34. In the February 28, 2005, bulletin, GM provided the following recommendations/instructions to its dealers – **but not to Brooke or the public in general:**

There is potential for the driver to inadvertently turn off the ignition due to low key ignition cylinder torque/effort. The concern is more likely to occur if the driver is short and has a large heavy key chain.

In the cases this condition was documented, the driver's knee would contact the key chain while the vehicle was turning. The steering column was adjusted all the way down. This is more likely to happen to a

person that is short as they will have the seat positioned closer to the steering column.

In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and to take steps, such as removing unessential items from their key chains, to prevent it.

Please follow this diagnosis process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

35. At that time, however, GM knew that the inadvertent turning off of the ignition in the vehicles was due to design defects in the Key System in those vehicles, including the Chevrolet Cobalt, and **was not** limited to short drivers using large heavy key chains.

36. GM failed to disclose and, in fact, concealed, the February 28, 2005 bulletin – and/or the information contained therein, from Chevrolet Cobalt owners, including Brooke, and sent affirmative representations to dealers that did not accurately describe the nature of the problem, the multiple design steps needed for a “sure solution” to the problem, and GM’s knowledge of it.

37. Indeed, rather than disclosing this serious safety problem that uniformly affected all Chevrolet Cobalt cars, GM, instead, concealed and obscured the problems, electing to wait until customers brought their cars to a dealership after an engine-stalling incident, and offered even its own dealers only an

incomplete, incorrect, and insufficient description of the defects and the manner in which to actually remedy them.

38. As of February 2005, GM engineers knew that the Saturn Ion and Chevrolet Cobalt vehicles had the Key System safety-related defects discussed in this Complaint.

39. Pursuant to 49 C.F.R. § 573.6, which requires an automobile manufacturer to “furnish a report to the NHTSA for each defect...related to motor vehicle safety,” GM had a duty, no later than February 2005 to disclose the safety-related defects in the Saturn Ion and Chevrolet Cobalt vehicles.

40. Instead of complying with its legal obligations, however, GM fraudulently concealed the Key System defect from the public – including Brooke – and continued to manufacture and sell Ions and Cobalts with these known safety defects, causing Brooke to continue to own a vehicle that contained a defective and dangerous Key System.

41. In March 2005, following its receipt of a customer complaint that his/her Cobalt vehicle ignition turned off while driving, GM opened another PRTS – Complete Report (0793/2005-US). Steve Oakley, the brand quality manager for the Cobalt, originated the PRTS. As part of the PRTS, Mr. Oakley reviewed an email dated March 9, 2005 from Jack Weber, a GM engineer. The subject of the email was “Cobalt SS Ignition Turn Off.” In the email Mr. Weber stated:

I've had a chance to drive a Cobalt SS and attempt to turn off the ignition during heel/toe down shifting. Much to my surprise, the first time I turned off the ignition switch was during a normal traffic brake application on I-96. After that I was able to do a static reproduction of the condition in a parking lot. I've attached photos of the condition with comments. My Anthropometric Measurements are attached below:

Static view of keys, fob and registration hitting knee.

Position of RKE fob during normal driving. Dynamic evaluation.

View of steering column cover and Pass Key 3+ "lump" under the key slot.

Key in run position, knee contacting the fob and the split ring is pulling on the key to move it to the "off" position. Static evaluation.

Fob has levered around the steering column cover and turned the ignition off.

Unobstructed view of the fob and column cover.

Attached below is documentation of a RAMSIS study performed to attempt to duplicate the real world condition.

Please call at (586) 986-0622 with questions.

Jack Weber

Mr. Weber clearly identified the defects in the Key System while he was driving the Cobalt.

42. Despite the clear evidence of the safety-related defect with the Key System, during the March 2005 PRTS, GM engineers decided not to reconsider any of the proposed solutions discussed during the February 2005 PRTS. Instead, the GM engineers leading the PRTS recommended that sole corrective action GM should recommend would be to advise customers to remove excess material from their key rings, **even though GM knew that the inadvertent turning off of the ignition in these vehicles was due to design defects in the Key System in those vehicles, and was not limited to drivers having excess key ring materials.**

43. In May 2005, GM, following its receipt of another customer complaint that his/her Cobalt vehicle ignition turned off while driving, it opened another PRTS.

44. During the May 2005 PRTS, GM decided to redesign the key in order to reduce the possibility that a driver may inadvertently turn the key from the “run” to the “accessory/off” position during ordinary driving.

45. Despite this initial safety/redesign commitment, however, GM ultimately failed to follow through on its own decision and closed this PRTS without any action, further concealing what it knew from the public and continuing to subject the public, including the Meltons, to the defective vehicles’ serious safety risks.

46. At or about this same time, GM, through Alan Adler, GM's Manager, Product Safety Communications, issued the following statement with respect to the Chevrolet Cobalt's inadvertent shut-off problems, affirmatively representing in its "Statement on Chevrolet Cobalt Inadvertent Shut-offs" that:

In rare cases when a combination of factors is present, a Chevrolet Cobalt driver can cut power to the engine by inadvertently bumping the ignition key to the accessory or off position while the car is running.

When this happens, the Cobalt is still controllable. The engine can be restarted after shifting to neutral.

GM has analyzed this condition and believes it may occur when a driver overloads a key ring, or when the driver's leg moves amid factors such as steering column position, seat height and placement. Depending on these factors, a driver can unintentionally turn the vehicle off.

Service advisers are telling customers they can virtually eliminate this possibility by taking several steps, including removing non-essential material from their key rings.

Ignition systems are designed to have "on" and "off" positions, and practically any vehicle can have power to a running engine cut off by inadvertently bumping the ignition from the run to accessory or off position.

GM's statement, however, was demonstrably false and misleading.

47. Contrary to GM's above-referenced statement, GM's internal testing documents showed that these incidents occurred when drivers were using

keys with the standard key fob. GM knew that these incidents were not caused by heavy key chains or a driver's size and seating position. GM knew that removing the non-essential material from key rings would not "virtually eliminate" the possibility of inadvertent bumping of the ignition key from the "run" to the "accessory/off" position while the car is running.

48. GM's above-referenced statement was further demonstrably false and misleading because GM knew that these incidents were ultimately caused by the safety-related defects in the Key System identified in the February 2005 PRTS.

49. But GM's affirmative concealment of the problems with the defective vehicles, including the Chevrolet Cobalt cars, did not end there.

50. On July 29, 2005, Amber Marie Rose, a sixteen year old Clinton, Maryland resident, was driving a 2005 Cobalt when she drove off the road and struck a tree head-on. Amber's driver's side frontal airbag did not deploy and she died as a result of the injuries she sustained in the crash.

51. GM received notice of Amber's incident in September 2005 and opened an internal investigation file pertaining to this incident shortly thereafter.

52. During its investigation of the incident, GM learned that the key in Amber's Cobalt was in the "accessory/off" position at the time of the crash.

53. During its investigation of the incident in which Amber was killed in her Cobalt vehicle, GM also knew that the driver's side frontal airbag

should have deployed given the circumstances of the crash. Upon information and belief, GM subsequently entered into a confidential settlement agreement with Amber's mother.

54. In December 2005, shortly after it commenced its internal investigation into the incident leading to Amber's death, GM issued a Technical Service Bulletin (05-02-35-007) (the "TSB").

55. The TSB, which GM affirmatively represented applied to 2005–2006 Chevrolet Cobalts, 2006 Chevrolet HHRs, 2005–2006 Pontiac Pursuit, 2006 Pontiac Solstices, and 2003–2006 Saturn Ions, provided, "Information on inadvertent Turning of Key Cylinder, Loss of Electrical System and no DTCs," provided the following service information:

There is potential for the driver to inadvertently turn off the ignition due to low ignition key cylinder torque/effort.


The concern is more likely to occur if the driver is short and has a large and/or heavy key chain. In these cases, this condition was documented and the driver's knee would contact the key chain while the vehicle was turning and the steering column was adjusted all the way down. This is more likely to happen to a person who is short, as they have the seat positioned closer to the steering column.

In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and should

take steps to prevent it - such as removing unessential items from their key chain.

Engineering has come up with an insert for the key ring so that it goes from a "slot" design to a hole design. As a result, the key ring cannot move up and down in the slot any longer - it can only rotate on the hole. In addition, the previous key ring has been replaced with a smaller, 13 mm (0.5 in) design. This will result in the keys not hanging as low as in the past.

56. An image of the insert changing the "slot" design to a "hole" design appears as follows:



57. As with its prior statement regarding the defective vehicles (see above), the information GM provided in this TSB was also false and misleading.

58. In the two PRTSs GM issued before it issued the TSB, GM engineers never represented that short drivers or heavy key chains were the reasons why these incidents were happening.

59. Indeed, at the time it issued the TSB, GM knew that these incidents were happening to drivers of all sizes using keys with the standard key fobs.

60. In other words, GM knew these incidents were not caused by short drivers with heavy key chains, but were caused by the safety-related defects in the Key System of its defective vehicles, including the Chevrolet Cobalt cars.

61. In 2005, GM began buying back Cobalts from certain customers who were experiencing engine stalling incidents. GM never told the public, including Brooke, that it was buying back Cobalts under these circumstances. GM refused to buy back Cobalts from other customers who had also experienced engine stalling incidents. In fact, for many of the customers who complained about experiencing engine-stalling incidents, GM never informed these customers of the TSB and/or the availability of the key insert.

62. On November 17, 2005, shortly after Amber's death and immediately before GM's issuance of the TSB, there was **another** incident involving a 2005 Cobalt in Baldwin, Louisiana. In that incident, the Cobalt went off the road and hit a tree. The frontal airbags did not deploy in this accident. GM received notice of this accident, opened a file, and referred to it as the "Colbert" incident.

63. On February 10, 2006, in Lanexa, Virginia, shortly after GM issued the TSB, a 2005 Cobalt drove off of the road and hit a light pole. As with the Colbert incident (above), the frontal airbags failed to deploy in this incident as well. The download of the SDM (the vehicle's "black box") showed the key was in the "accessory/off" position at the time of the crash. GM received notice of this accident, opened a file, and referred to it as the "Carroll" incident.

64. On March 14, 2006, in Frederick, Maryland, a 2005 Cobalt traveled off the road and struck a utility pole. The frontal airbags did not deploy in this incident. The download of the SDM showed the key was in the "accessory/off" position at the time of the crash. GM received notice of this incident, opened a file, and referred to it as the "Oakley" incident.

65. On August 1, 2006, following its receipt of a customer complaint about a Cobalt stalling while driving, GM opened yet another PRTS relating to this issue. GM closed this PRTS on October 2, 2006 however, without taking any action.

66. In October 2006, GM updated the TSB (05-02-35-007) to include additional model years: the 2007 Saturn Ion and Sky, 2007 Chevrolet HHR, 2007 Cobalt and 2007 Pontiac Solstice and G5. These vehicles had the same safety-related defects in the Key System as the vehicles in the original TSB.

All of the vehicles identified in the original TSB and updated TSB are hereinafter referred to as the "Defective Vehicles."

67. On December 29, 2006, in Sellenville, Pennsylvania, a 2005 Cobalt drove off the road and hit a tree. The frontal airbags failed to deploy in this incident. GM received notice of this incident, opened a file, and referred to it as the "Frei" incident.

68. On February 6, 2007, in Shaker Township, Pennsylvania, a 2006 Cobalt sailed off the road and struck a truck. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. GM received notice of this incident, opened a file, and referred to it as the "White" incident.

69. On August 6, 2007, in Cross Lanes, West Virginia, a 2006 Cobalt rear-ended a truck. The frontal airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the "McCormick" incident.

70. On September 25, 2007, in New Orleans, Louisiana, a 2007 Chevrolet Cobalt lost control and struck a guardrail. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the "Gathe" incident.

71. On October 16, 2007, in Lyndhurst, Ohio, a 2005 Chevrolet Cobalt traveled off road and hit a tree. The frontal airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the "Breen" incident.

72. On April 5, 2008, in Sommerville, Tennessee, a 2006 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. GM received notice of this incident, opened a file, and referred to it as the "Freeman" incident.

73. On May 21, 2008, in Argyle, Wisconsin, a 2007 Pontiac G5 traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. GM received notice of this incident, opened a file, and referred to it as the "Wild" incident.

74. On May 28, 2008, in Lufkin, Texas, a 2007 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the "McDonald" incident.

75. On September 13, 2008, in Lincoln Township, Michigan, a 2006 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a

frontal impact in this incident, the frontal airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the “Harding” incident.

76. On November 29, 2008, in Rolling Hills Estates, California, a 2008 Chevrolet Cobalt traveled off the road and hit a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the “Dunn” incident.

77. On December 6, 2008, in Lake Placid, Florida, a 2007 Chevrolet Cobalt traveled off the road and hit a utility pole. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the “accessory/off” position. GM received notice of this incident, opened a file, and referred to it as the “Grondona” incident.


78. In February 2009, GM opened yet another PRTS with respect to the Defective Vehicles – this time to investigate why the slot in the key in Cobalts allowed the key chain to hang too low in the vehicles, as well as the inadvertent shutting off of the vehicles.

79. Through this PRTS, GM determined that changing the key from a slot to a hole would significantly reduce the likelihood of inadvertent turning off the ignition switch.

80. In March 2009, GM approved of the design change in the key from the slot to a hole. According to GM, this redesigned change was

implemented in model year 2010 Chevrolet Cobalts. GM, however, chose not to provide these redesigned keys the owners or lessees of any of the vehicles implicated in the TSB, including the 2005 Cobalt.

81. This timeline gives a short overview of some key points between 2004 and the present, as discussed above:



82. Throughout this entire time period, GM was selling the Defective Vehicles to consumers for full price, and consumers were purchasing them believing that the vehicles were non-defective, but all the while GM was concealing the extent and nature of the defects in the Defective Vehicles.

**Old GM's Marketing Represented to the Public
that the Defective Vehicles Were Safe**


83. In a section called "safety," Old GM's Chevrolet website stated:

OUR COMMITMENT

Your family's safety is important to us. Whether it's a short errand around town or a cross-country road trip, Chevrolet is committed to keeping you and your family safe — from the start of your journey to your destination. That's why every Chevrolet is designed with a comprehensive list of safety and security features to help give you peace of mind. Choose from the safety features below to learn more about how they work, and which Chevy vehicles offer them.

84. Similarly, old GM promoted its Saturn vehicle line on television with statements like "Putting people first," and "Saturn. People First."

85. Saturn's print ad campaign featured advertisements like the following, which stated, among other things, "Need is where you begin. In cars, it's about things like reliability, durability and, of course, safety. That's where we started when developing our new line of cars":



86. In sum, in order to increase sales, old GM touted the safety of its vehicles.

87. But, when the time came for the company to stay true to its words, GM did not disclose its knowledge about the dangerous Key System defects to its customers, including Brooke.

Meet the New GM, Same as the Old GM

88. In 2009, GM declared bankruptcy and, weeks later, it emerged from bankruptcy. Both before and after GM's bankruptcy, the Key Systems in the Defective Vehicles continued to fail and GM, in all iterations, continued to conceal the truth.

89. On May 15, 2009, GM again met with Continental AG, an airbag component supplier, and requested that Continental download SDM data from a 2006 Chevrolet Cobalt accident where the airbags failed to deploy.

90. On December 31, 2010, in Rutherford County Tennessee, a 2006 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. GM received notice of this incident, opened a file, and referred to it as the "Chansuthus" incident.

91. On December 31, 2010, in Harlingen, Texas, a 2006 Chevrolet Cobalt traveled off the road and struck a curb. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the "Najera" incident.

92. On March 22, 2011, Ryan Jahr, a GM engineer, downloaded the SDM from Brooke's Cobalt. The information from the SDM download showed that the key in Brooke's Cobalt turned from the "run" to the "accessory/off" position 3-4 seconds before the crash.

93. On December 18, 2011, in Parksville, South Carolina, a 2007 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download

of the SDM showed the key was in the “accessory/off” position. GM received notice of this incident, opened a file, and referred to it as the “Sullivan” incident.

94. These incidents are not limited to vehicles of model year 2007 and before. According to GM’s own investigation, there have been over 250 crashes involving 2008-2010 Chevrolet Cobalts in which the airbags failed to deploy.

GM Investigates Further, but Continues to Conceal the Defect

95. In 2010, GM began a formal investigation of the frontal airbag non-deployment incidents in Chevrolet Cobalts and Pontiac G5s. GM subsequently elevated the investigation to a Field Performance Evaluation (“FPE”).

96. In August 2011, GM assigned Engineering Group Manager, Brian Stouffer as the Field Performance Assessment Engineer (“FPAE”) to assist with the FPE investigation.

97. In Spring 2012, Stouffer asked Jim Federico, a high level executive and chief engineer at GM, to oversee the FPE investigation. Federico was the “executive champion” for the investigation to help coordinate resources for the FPE investigation.

98. In May 2012, GM engineers tested the torque on the ignition switches for 2005-2009 Cobalts, 2007 and 2009 Pontiac G5s, 2006-2009 HHRs,

and 2003-2007 Ion vehicles in a junkyard. The results of these tests showed that the torque required to turn the ignition switches in most of these vehicles from the “run” to the “accessory/off” position did not meet GM’s minimum torque specification requirements, including the 2008-2009 vehicles. These results were reported to Stouffer and other members of the FPE.


99. In September 2012, Stouffer requested assistance from a “Red X Team” as part of the FPE investigation. The Red X Team was a group of engineers within GM assigned to find the root cause of the airbag non-deployments in frontal accidents involving Chevrolet Cobalts and Pontiac G5s. By that time, however, it was clear that the root cause of the airbag non-deployments in a majority of the frontal accidents was the defective Key System. The Red X Team became involved in the investigation shortly after Mr. Stouffer’s request.

100. During the field-performance-evaluation process, GM determined that, although increasing the detent in the ignition switch would reduce the chance that the key would inadvertently move from the “run” to the “accessory/off” position, it would not be a total solution to the problem.

101. Indeed, the GM engineers identified several additional ways to actually fix the problem. These ideas included adding a shroud to prevent a driver’s knee from contacting the key, modifying the key and lock cylinder to orient the key in an upward facing orientation when in the run position, and adding

a push button to the lock cylinder to prevent it from slipping out of run. GM rejected each of these ideas.

102. The photographs below are of a GM engineer in the driver's seat of a Cobalt during the investigation of Cobalt engine stalling incidents.



103. These photographs show the dangerous condition of the position of the key in the lock module on the steering column, as well as the key with the slot, which allow the key fob to hang too low off of the steering column. GM engineers understood that the key fob may be impacted and pinched between the driver's knee and the steering column which causes the key to be inadvertently turned from the run to accessory/off position. The photographs show why the GM engineers understood that increasing the detent in the ignition switch would not be a total solution to the problem. It also shows why GM engineers believed that the

additional changes to the Key System (such as the shroud) were necessary to fix the defects with the Key System.

104. The GM engineers clearly understood that increasing the detent in the ignition switch alone was not a solution to the problem but GM concealed – and continued to conceal – from the public, the nature and extent of the defects.

105. By 2012, Federico, Stouffer, and the remaining members of the Red X Team knew that the Key System in the Ion, the Cobalt, and the G5 vehicles had safety-related defects that would cause the key to move from the “run” to the “accessory/off” position while driving these vehicles. They also knew that when this happened the airbags would no longer work in frontal crashes.

106. Federico, Stouffer, and the other members of the Red X Team also understood that these safety-related defects had caused or contributed to numerous accidents and multiple fatalities. Despite this knowledge, GM chose to conceal this information from the public, NHTSA, and Plaintiffs.

107. Under 49 C.F.R. ¶ 573.6, GM had a duty in 2012 to disclose the safety-related defects in the Ion, Cobalt, and G5 vehicles. Rather than comply with their legal obligations, GM continued to fraudulently conceal these defects from the public and the U.S. government.

108. In December 2012, in Pensacola, Florida, Ebram Handy, a GM engineer, participated in an inspection of components from Brooke Melton’s

Cobalt, including the ignition switch. At that inspection, Handy, along with Mark Hood, a mechanical engineer retained by the Meltons, conducted testing on the ignition switch from Brooke Melton's vehicle, as well as a replacement ignition switch for the 2005 Cobalt.

109. At that inspection, Handy observed that the results of the testing showed that the torque performance on the ignition switch from Brooke Melton's Cobalt was well below GM's minimum torque performance specifications. Handy also observed that the torque performance on the replacement ignition switch was significantly higher than the torque performance on the ignition switch in Brooke Melton's Cobalt.

110. In January 2013, Handy, in preparation for a Rule 30(b)(6) deposition, spoke with several GM engineers, including DeGiorgio and Stouffer. At that time, Handy knew that, based on the testing he had observed, the original ignition switch in the 2005 Cobalt failed to meet GM's minimum torque performance specifications. GM knew that an ignition switch that did not meet its minimum torque performance requirements was a safety-related defect.

GM Fraudulently Conceals Evidence From The Meltons

111. On February 13, 2013, this Court entered an order compelling GM to produce certain documents, including all documents relating to the design

and testing of the ignition switch in the cars which were the subject of the initial TSB, including the 2007 Cobalt.

112. On February 28, 2013, GM produced what it said were all documents within its possession responsive to the Court's February 13, 2013 Order. GM did not produce any documents relating to any change in the ignition switch in the Cobalt, or any other Defective Vehicles, during the 2007 model year.

113. On April 29, 2013, the Meltons' counsel deposed Ray DeGiorgio, the chief design engineer for the ignition switches in the Defective Vehicles, in Detroit, Michigan. When asked whether there were any changes in the ignition switch in the Cobalt between model years 2005-2010, Mr. DeGiorgio testified:

Q. And that there weren't any changes made – or were there changes made to the switch between '05 and 2010 that would have affected the torque values to move the key from the various positions in the cylinder?

A. There was one change made to the resistor in '08, but that should not have affected the torque or the displacement of the switch.

I can restate this way: There was an electrical change made in '08, but not a mechanical change – at least there were no official changes, mechanical changes, made to the switch that I know of.

Q. When you say no official, could there be unofficial changes made?

A. I'm not saying that there was, I'm just saying if there was something changed at the supplier side, we were not aware of it and we did not approve it, okay?

(DeGiorgio Deposition, pp. 57-58).

114. Mr. DeGiorgio then testified about taking apart current production Cobalt ignition switches to determine whether there were any design changes GM was not aware of:

A. When I was approached by field investigation to provide a history or summary of the design changes, I wanted to make sure, you know, are there anything [sic] in the design that may have changed that we're not aware of? That's when I proceeded to take a couple of switches and take a look at it.

Q. And what did you find?

A. I saw nothing out of the norm that would suggest, you know, a potential issue.

Q. And what switches did you look at?

A. It was the Cobalt ignition switch.

Q. Which one? What model year?

A. I want to say these were current production switches because that's where they're available, so I want to say actually they were service parts, which we had just gotten.

(DeGiorgio Deposition, pp. 69-70).

115. At page 90, Mr. DeGiorgio reiterated that he was not aware of any changes in the ignition switches of 2005-2007 Cobalts:

Q. Do you know whether his '07 Cobalt, if it's the same ignition switch as was in the '05 and '06?

A. It came from the factory as is. I couldn't tell you if it was '05, '06 or '07. I'm not aware of any differences between the three. It's the original switch that came with the vehicle. How's that?

(DeGiorgio Deposition, p. 90).

116. Mr. DeGiorgio also testified he obtained Cobalt replacement ignition switches directly from the manufacturer, Delphi:

Q. Have you talked with anyone at Delphi regarding this – these reported incidents where they key moves from the run to the accessory position under certain driving conditions?

A. I did get ahold of Delphi, I did talk to Mary, and I had requested some ignition switches from her. Also, I was asked to investigate or look into, is Delphi still making the switch for GM or somebody else?

So I was in contact with Mary, I did get information such as, you know, do we still make the switches, were they made, and if I could get some switches from them.

Q. Did she say they're still making the switches?

A. They're still making the switches for service, GM service.

(DeGiorgio Deposition, p. 114)

Q. Okay. And what did you do with the switches that Ms. Fitz provided to you?

A. Again, I tore open a couple of these switches trying to see if there's anything blatantly different than might have been produced. I want to say, with the initial ION ignition switch. It

was like, are there any differences, you know, between the designs?

My intent was to look at the current switch and see if there's any changes that may have been made without our knowledge that would help explain, I want to say, this issue.

(DeGiorgio Deposition, p. 116).

117. Mr. DeGiorgio also provided the following additional testimony about Delphi:

Q. Did you ask Mary Fitz or anyone from Delphi whether there, in fact, had been any changes made to the ignition switch?

A. Yes, yes I did. And they came back, said there's been no changes made to the switch since the introduction to production.

Q. Who told you that?

A. Mary Fitz.

Q. Where is she located?

A. She's located in, I want to say, Delphi headquarters here in Michigan.

(DeGiorgio Deposition, pp. 117-118)

118. Mr. DeGiorgio's testimony left no doubt that he had spoken with Delphi employees and that they confirmed there were no changes made to the ignition switch in 2005-2010 Cobalts.

119. At his deposition, Mr. DeGiorgio was shown photographs of the differences between the ignition switch in Brooke's Cobalt and the ignition switch in the 2008 Cobalt or replacement ignition switch. After looking at the photographs of the different ignition switches, Mr. DeGiorgio testified as follows:

Q. The one on the right, Exhibit 13 is an '05 or an '06, and the one on the left, Exhibit 14, is either an '08 or replacement. Do you see the difference?

A. Yes.

Q. Have you noticed that before today, Mr. DeGiorgio?

A. No sir.

Q. Were you aware of this before today, Mr. DeGiorgio?

MR. HOLLADAY: Object to the form. You can answer.

THE WITNESS: No sir.

Q. It appears to be pretty clear that the plunger and the cap is taller on Exhibit 14 compared to Exhibit 13, isn't it?

A. That's correct.

Q. How is a taller cap going to affect the rotational resistance?

A. It's hard to determine from these pictures exactly if it is a taller cap or is it recessed inside the housing or not. It's hard for me to assess, really, what I'm looking at.

Q. You've taken apart a number of switches and you're telling the jury you've never noticed the difference in the plunger between the '05 and '06 versus the new resistor or switch?

MR. HOLLADAY: Object to the form.

THE WITNESS: I did not notice, no.

(DeGiorgio Deposition, pp. 149-150)

120. Mr. DeGiorgio was then further questioned about his knowledge of any differences in the ignition switches:

Q. And I'll ask the same question. You were not aware before today that GM had changed the spring – the spring on the ignition switch had been changed from '05 to the replacement switch?

MR. HOLLADAY: Object to the form. Lack of predicate and foundation. You can answer.

THE WITNESS: I was not aware of a detent plunger switch change. We certainly did not approve a detent plunger design change.

Q. Well, suppliers aren't supposed to make changes such as this without GM's approval, correct?

A. That is correct.

Q. And you are saying that no one at GM, as far as you know, was aware of this before today?

MR. HOLLADAY: Object. Lack of predicate and foundation. You can answer.

THE WITNESS: I am not aware about this change.

(DeGiorgio Deposition, pp. 151-152)

121. Mr. DeGiorgio signed his errata sheet on May 23, 2013. In the signed errata sheet, Mr. DeGiorgio did not change any testimony referenced in this

Complaint.

122. Mr. DeGiorgio's testimony left no doubt that he had absolutely no knowledge of any change in the ignition switch in 2005-2010 Cobalts.

123. On May 13, 2013, the Meltons served their Fifth Request for Production of Documents on GM. In RPD No. 1, the Meltons requested:

All documents and materials relating to GM's investigation into the change in the cap and spring in the 2005 Cobalt ignition switch to the cap and spring in the 2008 Cobalt ignition switch, as well as the replacement ignition switches for the Cobalt.

124. On June 17, 2013, GM filed its Response to the Fifth Request for Production of Documents. In response to RPD No. 1, GM stated:

As design release engineer Ray DeGiorgio testified, GM LLC did not request and was not asked to authorize or approve a change in the cap and spring in the ignition switch used in the 2008 Chevrolet Cobalt or in replacement ignition switches for the 2005-2007 Chevrolet Cobalt that would affect the torque required to move the key from the run to accessory position. GM LLC objects to this Request to the extent it seeks information protected from disclosure by the attorney-client privilege and/or the work product doctrine.

125. GM then approached the Meltons about mediating their case.

On August 21, 2013, the Meltons and GM attended the mediation at Bay Mediation.

126. Up to and including the date of the mediation, GM continued to state that no one at GM had authorized or approved any change to the ignition switch in 2005-2010 Cobalts.

127. The Meltons relied on the testimony of Mr. DeGiorgio, as well as the representations of GM and its attorneys, that no one from GM knew about any changes in the design of the ignition switch in 2005-2010 Cobalts.

128. The Meltons subsequently settled their claims against GM on August 22, 2013.

129. The Meltons executed the Settlement Agreement with GM on September 9, 2013.

130. On February 7, 2014, GM, in a letter from Carmen Benavides, Director – Product Investigations and Safety Regulations for GM, informed NHTSA that it was conducting Recall No. 13454 for certain 2005-2007 model year Chevrolet Cobalts and 2007 model year Pontiac G5 vehicles.

131. In its February 7, 2014, letter to NHTSA, GM represented that as replacement ignition switches became available, GM would replace the ignition switches on the Defective Vehicles.

132. On February 19, 2014, a request for timeliness query of General Motors' Safety Recall 13454 was sent to NHTSA. The timeliness query pointed out that GM had failed to recall all of the vehicles with the defective ignition switches.

133. The February 19, 2014, request for timeliness query also asked NHTSA to investigate GM's failure to fulfill its legal obligation to report the safety-related defects in the Defective Vehicles to NHTSA within five days of discovering the defect.

134. On February 24, 2014, GM in a letter from Carmen Benavides, informed NHTSA it was expanding the recall to include 2006-2007 model year (MY) Chevrolet HHR and Pontiac Solstice, 2003-2007 MY Saturn Ion, and 2007 MY Saturn Sky vehicles.

135. GM included an Attachment to the February 24, 2014 letter. In the Attachment GM, **for the first time**, admitted that GM authorized a change in the ignition switch in 2006. Specifically, GM stated:

On April 26, 2006, the GM design engineer responsible for the Cobalt's ignition switch signed a document approving changes to the ignition switch proposed by the supplier, Delphi Mechatronics. The approved changes included, among other things, the use of a new detent plunger and spring that increased torque force in the ignition switch. This change to the ignition switch was not reflected in a corresponding change in the part number for the ignition switch. GM believes that the supplier began providing the re-designed ignition switch to GM at some

point during the 2007 model year. (GM's February 24, 2014 letter and Attachment are attached as **Exhibit A.**)

136. GM then produced documents in response to Congressional requests leading up to the hearings April 1 and 2, 2014. Among the documents produced by GM is a document titled, "GENERAL MOTORS COMMODITY VALIDATION SIGN-OFF," dated April 26, 2006. This document is attached as **Exhibit B.** According to this document, Delphi had met all of the sign-off requirements in order to provide a new ignition switch for certain GM vehicles. GM has acknowledged that the ignition switch in the Cobalt was included in this design change.

137. The design change included a new detent plunger "to increase torque force in the switch." Mr. DeGiorgio's signature is on this page as the GM authorized engineer who signed off on this change to the ignition switch.

138. This GM Commodity Validation Sign-Off shows that Mr. DeGiorgio repeatedly perjured himself during his deposition on April 29, 2013. Mr. DeGiorgio perjured himself in order to fraudulently conceal evidence from the Meltons that GM had signed off on the change in the ignition switch so that the Meltons, and ultimately a jury, would never know that GM was changing the switches in 2007 and later model year Cobalts and concealing these changes from Brooke.

139. Mr. DeGiorgio perjured himself when he signed the errata sheet confirming that all the testimony was true and accurate.

140. GM fraudulently concealed this critical evidence of the design change in the ignition switch from the Meltons in its response to RPD No. 1 in Plaintiff's Fifth Request for Production of Documents wherein it said, "GM LLC did not request and was not asked to authorize or approve a change in the cap and spring in the ignition switch used in the 2008 Chevrolet Cobalt or in replacement ignition switches for the 2005-2007 Chevrolet Cobalt that would affect the torque required to move the key from the run to accessory position." GM served this response in its continuing effort to fraudulently conceal evidence from the Meltons that GM had signed off on the change in the ignition switch so that the Meltons, and ultimately a jury, would never know that GM was changing the switches in 2007 and later model year Cobalts and concealing these changes from Brooke.

Thornton's Role In Brooke's Injuries and Death

141. On March 6, 2010, Brooke took her 2005 Chevrolet Cobalt to Thornton for service because the engine shut off while she was driving. She told Thornton about her problems with the Cobalt, and confirmed to her father that she had explained to Thornton was happening with her Cobalt and that the engine was shutting off.

142. Despite having the GM TSB in their system, Thornton never found it and failed to discover that the Cobalt was shutting off because of the issues mentioned in the TSB.

143. Thornton performed work on Brooke's car, including a TBI injection clean on the vehicle. The TBI injection clean was not performed to correct the problem with the engine shutting off while driving. Thornton, however, told Brooke that it had performed the TBI injection clean in order to address the problem of the engine shutting off while she was driving. Thornton tried to sell Brooke other unnecessary and unneeded work on her car.

144. Based on the Miles In and the Miles Out on its service form, Thornton returned Brooke's car to her without even doing a test drive. Thornton, however, told Brooke that it had performed the TBI injection clean in order to address the problem of the engine shutting off while she was driving. Thornton never performed the work addressed in the GM TSB and never told Brooke about the GM TSB.

145. After she picked up her car, Brooke told her father that Thornton claimed to have repaired her Cobalt.

IV. Rescission

146. On June 24, 2011, the Meltons filed their original lawsuit against GM. On August 21, 2013, the Meltons mediated the case and agreed to

settle on August 22, 2013. The Meltons subsequently executed the Settlement Agreement with GM on September 9, 2013. The Meltons settled their case based on the information they had at the time, which did not include the information contained in Paragraph Nos. 135 to 140.

147. GM's fraudulent concealment of the evidence from the Meltons, as well as Mr. DeGiorgio's repeated perjury, resulted in the Meltons being misled about the true facts of the case and, thus, their settlement was based on incomplete false data that GM had withheld solely to induce them to settle their case.

148. On or about April 1, 2014, the Meltons learned that GM fraudulently concealed relevant evidence and affirmatively misled them, and that their settlement was based on incomplete and false data, and that GM had withheld that data solely to induce them to settle their case.

149. After reviewing the information now available because of the GM recall, the Meltons realized the full scope of GM's deception. On or about April 11, 2014, therefore, the Meltons tendered an offer of rescission to GM. The Meltons gave GM until April 20, 2014 to accept or deny the tender and rescission. GM responded on April 19, 2014 and declined the Meltons' offer of rescission.

V. Renewed Claims Against GM and Claims Against Thornton

The Meltons assert the following claims against GM:

Count One: Strict Liability

150. All preceding statements and allegations of Plaintiffs'

Complaint are incorporated herein and realleged as if expressly set forth herein.

151. GM designed, selected, inspected, tested, manufactured, assembled, equipped, marketed, distributed, and sold the Chevrolet Cobalt, and its components, including but not limited to, equipping it with the Key System.

152. GM designed, selected, inspected, tested, manufactured, assembled, equipped, marketed, distributed, and sold the Key System which was selected and installed in the Chevrolet Cobalt.

153. GM had a legal duty to design, inspect, test, manufacture, and assemble the Chevrolet Cobalt so that it would be reasonably crashworthy and provide a reasonable degree of occupant safety in foreseeable collisions occurring in the highway environment of its expected use.

154. Among other things, the 2005 Chevrolet Cobalt is not crashworthy, is defective, and is unreasonably dangerous and unsafe for foreseeable users and occupants in each of the following particulars:

- (a) having a Key System that is inadequately designed and constructed, and located, which may result in the key moving

from the run to accessory/off position during normal driving

maneuvers;

- (b) having a Key System that allows the Chevrolet Cobalt to stall or lose engine power, and steering and/or full braking ability while driving;
- (c) having frontal airbags that do not deploy when the key is in the accessory/off position;
- (d) failing to adequately warn Brooke, other consumers, or the public in general, about the unsafe and defective condition and design of the vehicle known to GM, so that individuals like Brooke and the Meltons could make informed and prudent decisions regarding traveling or riding in such vehicles.

155. The defective nature of the Chevrolet Cobalt was the proximate cause of the damages sustained by Brooke, and the Meltons, as set forth herein, thus rendering GM strictly liable.

Count Two: Negligence

156. All preceding statements and allegations of Plaintiffs' Complaint are incorporated herein and realleged as if expressly set forth herein.

157. GM was negligent in designing, inspecting, testing, manufacturing, assembling, marketing, selling and providing warnings for the Chevrolet Cobalt, as set out in the paragraphs above.

158. GM's negligence proximately caused the damages sustained by Brooke and the Meltons, as set forth herein.

Count Three: Breach of Implied Warranty

159. All preceding statements and allegations of Plaintiffs' Complaint are incorporated herein and realleged as if expressly set forth herein.

160. GM breached its implied warranty of merchantability by selling the Chevrolet Cobalt when it was not fit for the ordinary purpose for which such goods are sold.

161. This breach of warranty proximately caused the damages sustained by Brooke and the Meltons, as set forth herein.

Count Four: Fraud and Fraudulent Concealment

162. All preceding statements and allegations of Plaintiffs' Complaint are incorporated herein and realleged as if expressly set forth herein.

163. GM intentionally concealed material facts from Brooke and the Meltons, the public, and NHTSA. GM knew that the Chevrolet Cobalt and other GM vehicles were designed and manufactured with Key System defects, but GM concealed those material facts. Although the defective GM vehicles contain

safety-related defects that GM knew of, or should have known of, at the time of distribution, GM recklessly manufactured and distributed those vehicles to consumers in the United States. Those consumers had no knowledge of the safety-related defects.

164. GM had a duty to disclose the facts to Brooke, the public who owned defective GM cars, and NHTSA, but failed to do so.

165. GM knew that Brooke had no knowledge of those facts and that she did not have an equal opportunity to discover the facts. GM was in a position of superiority over Brooke. Indeed, Brooke trusted GM not to sell her a car that was defective or that violated federal law governing motor vehicle safety. Brooke further trusted GM to warn of defects and to recall defective vehicles timely and before they caused injury.

166. By failing to disclose these material facts, GM intended to induce Brooke to purchase the Chevrolet Cobalt and/or to continue to use and drive it. GM further intended to induce NHTSA not to recall Brooke's Cobalt, well as the other defective GM vehicles, in order to reduce its eventual financial exposure.

167. Brooke reasonably relied on GM's nondisclosure, and reasonably but unknowingly continued to use the Chevrolet 2005 Cobalt until the date of the wreck.

168. Brooke would not have purchased the Chevrolet Cobalt had she known of the Key System defects, and certainly would not have continued to drive it.

169. As a direct and proximate result of GM's wrongful conduct and fraudulent concealment, Brooke and the Meltons suffered the damages described herein, including the full economic and intangible value of the life of Brooke Melton to her had she lived.

170. GM's conduct was knowing, intentional, with malice, demonstrated a complete lack of care, and was in reckless disregard for the rights of Brooke and the Meltons, such that punitive damages are appropriate.

Count Five: Negligence of Thornton

171. All preceding statements and allegations of Plaintiffs' Complaint are incorporated herein and realleged as if expressly set forth herein.

172. On March 6, 2010, Brooke brought her Cobalt to Thornton for service because the engine shut off while she was driving. Thornton performed a TBI injection clean on the vehicle and led Brooke to believe that this service would resolve the problem of the engine shutting off while driving.

173. Thornton was, or should have been, aware of the TSB which applied to Brooke's vehicle. Thornton, however, did not perform the work pursuant to the TSB.

174. Thornton knew, or should have known, that not performing the TSB work would result in the Chevrolet Cobalt being unsafe to drive because there was the potential that the key could move from the run to accessory position due to the low ignition key cylinder torque effort.

175. On March 10, just before the collision which resulted in Brooke's death, the key in the Cobalt turned from the run to the accessory position which ultimately caused Brooke to lose control of the Cobalt.

176. Thornton's negligence in failing to properly diagnose the source of the Chevrolet Cobalt's engine shutting off, as well as its decision to return the Cobalt to Brooke without having diagnosed and fixed the problem, was a proximate cause of the damages sustained by Plaintiffs, as set forth herein.

Count Six: Punitive Damages

177. All preceding statements and allegations of Plaintiffs' Complaint are incorporated herein and realleged as if expressly set forth herein.

178. GM, through its conduct in designing, testing, manufacturing, assembling, marketing, selling, and failing to adequately repair the Cobalt, demonstrated an entire want of care, evidencing a reckless indifference and disregard to the consequences of their actions. GM's actions also constitute fraudulent concealment.

179. Thornton, in failing to find and employ the TSB, in repairing the wrong part of Brooke's car, and failing to test drive the car, and in failed to properly apprise her of the remaining issues in her car and of the fact they had not safely repaired it, Thornton demonstrated an entire want of care, evidencing a reckless indifference and disregard to the consequences of their actions.

180. Plaintiffs, pursuant to O.C.G.A. § 51-12-5.1, are entitled to an award of punitive damages to deter GM and Thornton, and other similarly situated entities, from such conduct in the future.

Count Seven: Attorney's Fees and Expenses

181. All preceding statements and allegations of Plaintiffs' Complaint are incorporated herein and realleged as if expressly set forth herein.

182. GM's and Thornton's actions have been in bad faith and have caused Brooke and the Meltons to suffer unnecessary trouble and expense. Brooke and the Meltons are, therefore, entitled to recover from GM all expenses of litigation, including attorney's fees, costs and expenses pursuant to O.C.G.A. § 13-6-11.

V. Damages

183. All preceding statements and allegations of Plaintiffs' Complaint are incorporated herein and realleged as if expressly set forth herein.

184. Kenneth David Melton and Mary Elizabeth Melton, the natural parents of Jennifer Brooke Melton, deceased, have standing to recover for the wrongful death of Jennifer Brooke Melton.

185. Kenneth David Melton and Mary Elizabeth Melton, as Administrators of the Estate of Jennifer Brooke Melton, have standing to recover the general damages and special damages of Jennifer Brooke Melton.

186. As a direct and proximate result of the negligence and misconduct of both Defendants, as well as the defective, unsafe and unreasonably dangerous Cobalt, Jennifer Brooke Melton was killed, and Plaintiffs are entitled to recover from all the Defendants the full value of the life of Brooke.

187. As a direct and proximate result of the negligence and misconduct of both Defendants, as well as the defective, unsafe and unreasonably dangerous Cobalt, Brooke experienced physical pain and suffering.

188. As a direct and proximate result of the negligence and misconduct of both Defendants, as well as the defective, unsafe and unreasonably dangerous Cobalt, Brooke experienced mental pain and suffering, including shock, fright, and terror.

189. As a direct and proximate result of the negligence and misconduct of both Defendants, Brooke's Estate incurred funeral and burial expenses.

Prayer For Relief

Plaintiffs, the Meltons, demand judgment and other relief as follows:

a. Judgment against GM and Thornton in an amount sufficient to fully and fairly compensate Brooke's Estate and the Meltons for her physical and emotional injuries, her medical bills and funeral expenses, all of her general and special damages, and for the full value of her life.

b. Punitive damages against both GM and Thornton pursuant to O.C.G.A. § 51-12-5.1;

c. Attorney's fees and costs of litigation from both GM and Thornton pursuant to O.C.G.A. § 13-6-11;

d. Trial by jury; and

e. Such other relief as the Court deems just and proper under the circumstances.

DATED: May 12, 2014.

Respectfully submitted,

THE COOPER FIRM


Lance A. Cooper

Georgia Bar No. 186100


Patrick A. Dawson

Georgia Bar No. 005620

Of Counsel

531 Roselane Street
Suite 200
Marietta, GA 30060
(770) 427-5588

**BEASLEY, ALLEN, CROW, METHVIN,
PORTIS & MILES, P.C.**


Benjamin E. Baker, Jr.

Georgia Bar No. 032926

Of Counsel

218 Commerce Street
Post Office Box 4160
Montgomery, AL 36104
(334) 269-2034

SHERROD & BERNARD, P.C.


Kenneth R. Bernard, Jr.

Georgia Bar No. 054844

8470 Price Avenue
P.O. Box 1154
Douglasville, Georgia 30133-1154
(770) 920-8350

Attorneys for Plaintiffs